


HOW TO USE MOTION MANAGER


1. Firmware update

In order to use the motion manager feature of TBS1 NiLAB servo drive, you must update the drive with the last firmware release.

Go to Device menu and select Download.....




Then select the file to download and press the download button in the download device FW File.



2. Fill the required registers to arrange the motion sequence

Go to the Data – Parameter window and fill the register starting from Tag 470.




| Modbus Address | Tag | Name | Value | Unit |
|----------------|-----|----------------------------|-------|------|
| 01D5 | 469 | P469 | 0 | |
| 01D6 | 470 | 0 Task Target Position | 10000 | |
| 01D7 | 471 | P471 | 0 | |
| 01D8 | 472 | 0 Target Velocity | 16960 | |
| 01D9 | 473 | P473 | 15 | |
| 01DA | 474 | 0 Target Acc | 44096 | |
| 01DB | 475 | P475 | 39 | |
| 01DC | 476 | 0 Target Dec | 44096 | |
| 01DD | 477 | P477 | 39 | |
| 01DE | 478 | 0 Position Window | 500 | |
| 01DF | 479 | P479 | 0 | |
| 01E0 | 480 | 0 Position Window Time | 50 | |
| 01E1 | 481 | 0 Next Task | 1 | |
| 01E2 | 482 | 0 Concatenate Next Profile | 0 | |
| 01E3 | 483 | 0 Wait Time Before Next | 0 | |
| 01E4 | 484 | 0 word1 | 0 | |
| 01E5 | 485 | 0 word2 | 0 | |
| 01E6 | 486 | 1 Task Target Position | 14464 | |
| 01E7 | 487 | P487 | 1 | |
| 01E8 | 488 | 1 Target Velocity | 16960 | |
| 01E9 | 489 | P489 | 15 | |
| 01EA | 490 | 1 Target Acc | 44096 | |
| 01EB | 491 | P491 | 39 | |
| 01EC | 492 | 1 Target Dec | 44096 | |
| 01ED | 493 | P493 | 39 | |
| 01EE | 494 | 1 Position Window | 500 | |
| 01EF | 495 | P495 | 0 | |
| 01F0 | 496 | 1 Position Window Time | 50 | |
| 01F1 | 497 | 1 Next Task | 2 | |
| 01F2 | 498 | 1 Concatenate Next Profile | 0 | |
| 01F3 | 499 | 1 Wait Time Before Next | 0 | |
| 01F4 | 500 | 1 word1 | 0 | |
| 01F5 | 501 | 1 word2 | 0 | |
| 01F6 | 502 | 2 Task Target Position | 34464 | |
| 01F7 | 503 | P503 | 1 | |
| 01F8 | 504 | 2 Target Velocity | 16960 | |
| 01F9 | 505 | P505 | 15 | |
| 01FA | 506 | 2 Target Acc | 44096 | |
| 01FB | 507 | P507 | 39 | |
| 01FC | 508 | 2 Target Dec | 44096 | |
| 01FD | 509 | P509 | 39 | |

Any motion tasks are composed by these registers:


| Task number | Parameter | Value |
|-------------|--------------------------|---|
| n | Target position | Counts |
| n | Target Velocity | Counts/sec per pole/pitch -> for example 65536 is 1 pole pitch per seconds (1 pole pitch in NL080i is 30 mm) |
| n | Target Acc | Counts/sec^2 |
| n | Target Dec | Counts/sec^2 |
| n | Position Window | Counts |
| n | Position window time | msec |
| n | Next task | Number of the successive task to go. For example for two position (0 -> 1) In the last motion task (1->0) |
| n | Concatenate next profile | If this is set to 1 the next task is executed, if this is set to 0 the bit4 of the command word must be toggle. |
| n | Wait time before next | msec |


3. Select the OPMODE on the drive

Go to the OPMODE list and select Motion Tasks modality.




Then select the Diagnostic mode to use the Motion task debug window. Go to Administration and set the password **fpcb**.





Then do to Tools and selection Motion Manager.




Using the motion manager you are able to set the bit of the control word manually to start homing and the sequence.


4. Homing the motor axis

Before starting the motion sequence you need to define the zero position of the axis.

So, select the mode of operation to Homing




Then the most simple way is to do homing is select the homing method to 35. Current position



Then click on the corresponding led to bit0 to enable the drive and then toggle the bit4. The leds must become green to set and gray if are not setted. After bit4 is toggled the position must be close to 0 counts. Then disable the drive clicking on the bit0.

5. Start the motion sequence

Then select the mode of operation to 1: Profile position



Then enable the drive clicking on bit0 and then on bit4 to start the sequence.

If the concatenate next task is set to 0 the motor moves of 1 step and remaining in position until a new bit4 toggle is performed from this interface.