

Connection system

This page describes the **connection system** of the GDM linear unit. The unit is provided with a power cable and a signal cable with PTC sensor connections.

Power cable - DE20001270-5M

The GDM linear unit is provided with two cables: a power cable and a signal cable with PTC sensor connections.





Note: The thermal switch connections can also be in black color. In this case the cross-section of these wires is smaller than the motor phase wires.

Signal cable



Note: This signal cable can be provided with the connector type used by the servo drive.

Function	Cable wire colors
0 VDC	Black
+5VDC $\pm$ 5%	Red
SIN+	Yellow
SIN-	Blue

COS+	Green
COS-	Orange
Shielding	Shield

Wiring notes

- The **power cable** carries the motor phases and the thermal (PTC) sensor connections. - The **signal cable** carries the encoder signals (SIN/COS) and the 0 VDC / +5 VDC supply. - The thermal switch wires may be black with a smaller cross-section than the phase wires. - The signal cable can be supplied with the connector type used by the servo drive.

From:

<https://dokuwiki.nilab.at/> - **NiLAB GmbH**
Knowledgebase

Permanent link:

https://dokuwiki.nilab.at/doku.php?id=en:gdm_linear_axes:connection_system

Last update: **2026/09/11 07:54**

