








# MBM Connectors on motor side



## M17 type connectors

|                                                                                   |                                                                                   |                                                                                    |                                                                                     |
|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
|  |  |  |  |
| Fixed side<br>Feedback E - external<br>view                                       | Flying side<br>Feedback P - external<br>view                                      | Fixed side<br>Motor phases - external<br>view                                      | Flying side<br>Motor phases - external<br>view                                      |
|                                                                                   | <b>ASTA 876 - 09010002</b>                                                        |                                                                                    | <b>BSTA 861 - 09020002</b>                                                          |

## M23 type connectors

|                                                                                    |                                                                                    |                                                                                     |                                                                                      |
|------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
|  |  |  |  |
| Fixed side<br>Feedback E - external<br>view                                        | Flying side<br>Feedback P - external<br>view                                       | Fixed side<br>Motor phases - external<br>view                                       | Flying side<br>Motor phases - external<br>view                                       |
|                                                                                    | <b>ASTA 014 - 09010005</b>                                                         |                                                                                     | <b>BSTA 085 - 09020004</b>                                                           |

## M40 type connectors (Power only)

|                                                                                     |                                                                                     |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
|  |  |
| Fixed side<br>Motor phases - external<br>view                                       | Flying side<br>Motor phases - external<br>view                                      |
|                                                                                     | <b>CSTA 263 FR5244 - 09020005</b>                                                   |

From:

<https://dokuwiki.nilab.at/> - **NiLAB GmbH**  
**Knowledgebase**

Permanent link:

[https://dokuwiki.nilab.at/doku.php?id=en:mbm\\_motors:motor\\_connectors](https://dokuwiki.nilab.at/doku.php?id=en:mbm_motors:motor_connectors)

Last update: **2026/09/11 07:57**

