


Connectors



Rotoliner motor has 3 x M12 connectors (standard version) and 4 x M12 connectors (CanOPEN version).

L1 and L2 are the status led for linear and rotary motor.

Connector	Function	Type
C1	Power connector	M12, 5 poles male
C2	Signal connector for linear side	M12, 8 poles female
C3	Signal connector for rotary side	M12, 8 poles female
C4	CanOPEN connector	M12, 5 poles female

For pinout of the connectors on the relative cable, please see:

https://www.nilab.at/dokuwiki/doku.php?id=integrated_drive_motors:connection_system

From:

<https://dokuwiki.nilab.at/> - NiLAB GmbH
Knowledgebase

Permanent link:

https://dokuwiki.nilab.at/doku.php?id=integrated_rotoliner:connections

Last update: **2024/09/23 07:54**

